



Instructions for replacing the power supply in a CG635

Tools needed:

Phillips head screw driver

- 1. Remove the top cover.**
- 2. Remove the 3 screws securing the power supply to the chassis .**
- 3. Pull out the old power supply.**
- 4. Install the new power supply.**
- 5. Install the screws securing the power supply to the chassis.**
- 6. Install the top cover.**